



ACTIONS ▼

---

**2018 KOMATSU**  
**D51PX-24**  
TRACK TYPE TRACTORS

---

---

**Serial #:** B20126  
**SMU / Hours:** 4,790

Owensboro, KY, United States



FEATURES

CONDITION

NOTES

●●● Good ●● Fair ● Poor

Approved Repair

[-] Collapse All

[-] GENERAL APPEARANCE

●●● Battery Box

●●● Cab or Canopy

●●● Draw Bar

●●● Fuel Tank

●●● Hard Nose P&B

●●● Paint

●●● Sheet Metal

●●● Belly Pans

●●● Counterweight

●●● Engine Enclosures

●●● Grab Irons

●●● Hood

●●● Pre-Cleaner Bowl

●●● Steps / Ladder

●●● Bumper

●●● Decals

●●● Fenders

●●● Guards

●●● Main Frame Welds

●●● Radiator Grill

●●● Transmission Guard

NO Cleaning Required

NO S.O.S. Taken

[-] SAFETY ITEMS



Back Up Alarm



Beacon / Strobe



Horn

Parking Brake - SAFETY  
ITEMS

Rear View Camera



Safety Locks / Pins



Seat Belt / Date

**YES**

ROPS

**YES**Safety Decals In Place /  
Legible**GAUGES, OPERATOR STATION, CONSOLE**

Air Conditioner



Dash Console



Door Latches / Seals



EMS Panel / Warnings



Floor Boards / Mats



Gauges



Glass/Mirrors



Headliner



Heater



Interior Lights



Meter Replaced / Working



Monitoring Panel / Display



Radio Type &amp; Condition



Seat Cushion / Arm Rest

Seat Suspension Type /  
Condition

Switches



Windshield Wipers

**YES**

Current O&amp;MM

**NO**

Current Parts Manual

**NO**

Current Safety Manual

**ENGINE**

Air Cleaners



Anti-Freeze Color / Level



Engine Supports



Exhaust / Muffler / Stack



Fuel Injection System



Governor / Control



Operating Condition - ENGINE



Turbocharger / Blower

Oil Filter Condition / Service  
Hours

<b>NO</b>	Blow By	<b>YES</b>	Compression in Radiator	<b>NO</b>	Emissions Decal Legible
<b>YES</b>	Fluid Levels OK?	<b>NO</b>	Has Engine been rebuilt?	<b>NO</b>	Knocking
<b>NO</b>	Oil Leaks	<b>NO</b>	Pre Lube System	<b>NO</b>	Water in Oil

---

**— EMISSIONS**

<b>●●●</b>	After Treatment System	<b>●●●</b>	DPF Condition / Hours Changed
<b>NO</b>	Leaks / Type		

---

**— COOLING SYSTEM**

<b>●●●</b>	Belts / Pulleys - COOLING SYSTEM	<b>●●●</b>	Coolers	<b>●●●</b>	Fan
<b>●●●</b>	Fan Drive / Type	<b>●●●</b>	Hoses	<b>●●●</b>	Radiator
<b>●●●</b>	Shroud / Guards	<b>●●●</b>	Water Pump		
<b>NO</b>	Folded Core Radiator	<b>NO</b>	Leaks - COOLING SYSTEM	<b>NO</b>	Modular Radiator
<b>NO</b>	Sand Blast Grid	<b>YES</b>	Standard Radiator		

## — ELECTRICAL, STARTING AND CHARGING SYSTEM

●●●	Alternator	●●●	Batteries / Cables	●●●	Pre-Heater
●●●	Product Link / Condition	●●●	Starter	●●●	Wiring
●●●	Work Lights				
<b>NO</b>	Active Codes	<b>NO</b>	Block Heater	<b>NO</b>	Ether Aid
<b>NO</b>	Jump Start Terminal				

## — TRANSMISSION

●●●	Case	●●●	Controls - TRANSMISSION	●●●	Cooler
●●●	Lines / Fittings - TRANSMISSION	●●●	Operating Condition - TRANSMISSION	●●●	Pump - TRANSMISSION
●●●	Seals	●●●	Temp / Pressure Gauges	●●●	Torque Converter (Stall Speed)
●●●	Transmission - Forward Shifts	●●●	Transmission - Reverse Shifts	●●●	Transmission Oil Filter Condition / Service Hours
●●●	Valves				
<b>YES</b>	Auto Shift	<b>YES</b>	Hydrostatic	<b>NO</b>	Leaks - TRANSMISSION
<b>YES</b>	Multi Velocity Shift Program	<b>NO</b>	Powershift	<b>YES</b>	Traction Control
<b>NO</b>	Transmission - Noisy				

## — STEERING



Differential Steering Controls



Pump / Motor



Steering Clutch



Steering Linkage



Steering Operating Condition



Steering Valve

## — BRAKE



Parking Brake Operation



Service Brake Operation

## — HYDRAULICS



Angle Cylinder

Control Linkage -  
HYDRAULICS

Hose Lines

Hydraulic Oil Filter Condition /  
Service Hours

Hydraulic Valves



Lift Cylinders



Mounts / Yokes



Overall Operating Condition



Pumps



Tank / Sight Glass / Cap



Tilt Cylinder

**NO**

Leaks - HYDRAULICS

## — BLADE



Back of Blade



C Frame / Mounts / Bearings



Cutting Edge &amp; Bits



Face / Moldboard



Knuckle



Pins



Push Arm



Single Tree



Spill Rack



Stabilizer Link



Tilt Arms



Tower



Trunnions

---

**— UNDERCARRIAGE**



Guiding Guard - Left



Guiding Guard - Right



Track Frame - Left



Track Frame - Right

**NO** Pins & Bushings Turned?

Average Life Remaining -

UNDERCARRIAGE

80% - UC Repalce 1,500 hours ago