



ACTIONS ▼

2020 KOMATSU
PC360LC-11
EXCAVATOR

Serial #: A38095
SMU / Hours: 4,247



FEATURES CONDITION NOTES

●●● Good ●● Fair ● Poor

Approved Repair

[-] Collapse All

[-] GENERAL CONDITION

●●●	Body	●●●	Frame	●●●	General
NO	ET Product Status Report Download	YES	Machine Starts and is Operable	NO	S.O.S. (All Compartments)
NO	VIDS/VIMS Download Available				

[-] GENERAL APPEARANCE

●●●	Bumper	●●●	Cab or Canopy	●●●	Car Body
●●●	Catwalk	●●●	Counterweight	●●●	Crankcase Guard / Battery Box
●●●	Draw Bar	●●●	Eng. Enclose Hood / Stack	●●●	Engine Doors

- Fenders
- Grab Irons
- Paint
- Radiator Grill & Shroud

- Fiberglass
- Hood
- Plastic
- Sheet Metal

- Fuel Tank
- Main Frame Welds
- Pre-Cleaner Bowl
- Steps / Ladder

NO Cleaning Required

NO Extra Fuel Tanks

NO S.O.S. Taken

SAFETY ITEMS

- Brake Hold
- Parking Brake
- Swing Brake

- Glass / Mirrors
- ROPS

- Horn
- Seat Belt - SAFETY ITEMS

YES Back Up Alarm Functioning

YES Brakes Functioning

NO Cab Guards

YES ROPS

YES Safety Decals In Place

YES Safety Decals Legible

OPERATOR STATION

- Air Conditioner
- Door Latches & Hinges
- Floor Mats
- Heater
-

- Dash Console
- EMS Panel / Warnings
- Gauges
- Interior Lights
- Seat Cushion / Arm Rest

- Door Latches
- Floor Boards
- Glass/Mirrors
- Meter
- Switches

Seat Belt - OPERATOR STATION



Travel Controls (Type)



Windshield Wipers

YES

Back Up Alarm

YES

Current O&MM

NO

Current Parts Manual

NO

Current Safety Manual

YES

ROPS Certification Plate

ENGINE



Air Cleaners



Belts / Pulleys - ENGINE



Engine Supports



Exhaust / Muffler



Fuel Injection System



Fuel System



Governor



Operating Condition - ENGINE



Turbocharger



Turbocharger / Blower

NO

Apparent Other Engine Damage

NO

Blow By

YES

Compression in Radiator

NO

Emissions Decal

YES

Engine Oil Level Full

YES

Fluid Levels OK?

NO

Fuel Leaks

NO

Knocking

NO

Oil filter Cut and Inspected

NO

Oil Leaks

NO

Water in Oil

COOLING SYSTEM



Coolers



Fan

Belts / Pulleys - COOLING SYSTEM



Fan Drive



Hoses



Hoses & Tubes - COOLING SYSTEM



Hydraulic Fan Drive



Radiator



Water Pump

NO

Leaks

— ELECTRICAL, STARTING AND CHARGING SYSTEM



Alternator



Batteries / Cables



Lighting



Pre-Heater



Starter



Starter Air



Starter Electric



Wiring

YES

Block Heater

YES

Ether Aid

— HYDRAULICS



Boom Cylinder



Bucket Cylinder



Control Linkage



Hose Lines



Hoses & Tubes - HYDRAULICS



Hydraulic Swivel



Operating Condition - HYDRAULICS



Pump Drive



Pumps & Valves



Rotex - HYDRAULICS



Rotex - HYDRAULICS 1



Stick Cylinder



Swing Gear



Swing Motors



Tank

 Travel Motors




- BOOM & STICK

 Boom Lower Pins & Bushings	 Boom Upper Pins & Bushings	 Stick Pins & Bushings (Boom End)
 Stick Pins & Bushings (Bucket End)		
NO Boom Cracked	NO Stick Cracked	







- BOOM

 Boom Condition	 Boom Pins	 Pins & Bushings - BOOM
--	---	--

- STICK

 Pins & Bushings - STICK	 Stick Conditions	 Stick Pins
---	--	--

- BUCKET

 Bucket Bottom	 Bucket Door	 Bucket Linkage
 Bucket Mounts	 Bucket Sides	 Cutting Edges
 Teeth / Adapters		
YES Quick Coupler		

Width
54"

— UNDERCARRIAGE



Track Frame - Left



Track Frame - Right

NO

Pins & Bushings Turned?

Average Life Remaining -
UNDERCARRIAGE
50%

— FINAL DRIVES



Drive Motors



Housings



Planetaries



Planetaries / Diff

NO

Chip Detectors Operational

NO

Left Final Drive Mag Plug
Inspected

NO

Right Final Drive Mag Plug
Inspected

— COMMENTS, MISC. REPAIRS, GENERAL REMARKS

comment 1
3D Topcon grade control